



joined to the surrounding fiber- or fabric-reinforced plastic so that the permanent magnets and the machine shaft form a dimensionally stable unit.